

## SERVICE BULLETIN

**Ref. No:** SV2011-001 **Issued Date:** 20/10/11  
**To:** All Sail boat owners with YANMAR engine **Page:** 1/1  
**Subject:** YANMAR Sailing Operation and Engine Stopped

Y

anmar advise that During Sailing Operation and Engine Stopped;

- Yanmar Mechanical Gear Boxes and Sail Drives using Fixed blade propellers, Control Lever must be in **Neutral** with lever in reverse failure of Drive Cone can occur
- Yanmar Mechanical Gear Boxes and Sail Drives using Folding or Feathering propellers, Control lever can be put in reverse to enable the Propeller to either feather / fold, and then moved back to **Neutral**.

***The Lee Marine Service Dept. therefore recommends that when a yacht fitted with Yanmar Mechanical Gear Boxes and Sail Drives is under sail the gear control lever is left in Neutral.***

Anthony Gates

Service Manager